

008 - Bridge Serial Number	County	007B - Facility Carried by Structure	006A - Features Intersected	Activity Name	Priority	Location	Comments	Completion Date	004 - Place Code
035-0017-0	Butts	STARK ROAD	YELLOW WATER CREEK	800 - BRIDGE JOINT SEALING	C	Bent 2 Joint	Clean and seal bent 2 joint		0000
035-0018-0	Butts	STARK ROAD	YELLOW WATER CREEK TRIB	821 - CULVERT REPAIR	B	Inlet wing	Repair inlet wing wall		0000
035-0018-0	Butts	STARK ROAD	YELLOW WATER CREEK TRIB	845 - OTHER BRIDGE MAINT	B	Both barrels	Remove silt from inside barrels.		0000
035-0019-0	Butts	BARNETTS BRIDGE RD	JACKSON LAKE	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Beams and bearings	Steel beams and bearings need to be cleaned and painted.		0000
035-0019-0	Butts	BARNETTS BRIDGE RD	JACKSON LAKE	550 - EROSION CONTROL	B	Abutment #4	Repair erosion under Abutment #4 cap		0000
035-0019-0	Butts	BARNETTS BRIDGE RD	JACKSON LAKE	800 - BRIDGE JOINT SEALING	C	Abutment #1, bent 2 and 3 joints	Repair Abutment #1 joint; seal intermediate deck joints.		0000
035-0019-0	Butts	BARNETTS BRIDGE RD	JACKSON LAKE	830 - REP MAIN STRUCT MEMBERS	B	Bearings and masonry plates at both abutments	Repair bearings and masonry plates with sheet corrosion and section loss at both abutments.		0000
035-0021-0	Butts	HALLS BRIDGE ROAD	YELLOW WATER CREEK	800 - BRIDGE JOINT SEALING	C	Deck Joints	Deck joints need to be cleaned and sealed.		0000
035-0021-0	Butts	HALLS BRIDGE ROAD	YELLOW WATER CREEK	810 - DECK REPAIR	B	Deck top	Repair spalls, moderate abrasion, and seal moderate cracks in the deck top.		0000
035-0021-0	Butts	HALLS BRIDGE ROAD	YELLOW WATER CREEK	815 - BRIDGE CURB/RAIL REPAIR	B	Span 3	Span 3 left, bridge rail spalled with exposed rebar and needs to be repaired.		0000
035-0021-0	Butts	HALLS BRIDGE ROAD	YELLOW WATER CREEK	845 - OTHER BRIDGE MAINT	B	Both abutments	Abutments have voids underneath the caps that need to be filled/repared.		0000
035-0022-0	Butts	HALLS BRIDGE ROAD	CANEY FORK CREEK	520 - BRUSH AND TREE CUTTING	C	All sides	Cut and remove vegetation		0000
035-0022-0	Butts	HALLS BRIDGE ROAD	CANEY FORK CREEK	845 - OTHER BRIDGE MAINT	B	Inlet and outlet	Repair scour inlet and outlet		0000
035-0022-0	Butts	HALLS BRIDGE ROAD	CANEY FORK CREEK	845 - OTHER BRIDGE MAINT	B	inlet, barrel 2	large tree in barrel 2, needs to be removed.		0000
035-0026-0	Butts	WOLF CREEK ROAD	WOLF CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Piles	Steel piles need to be cleaned and painted.		0000
035-0026-0	Butts	WOLF CREEK ROAD	WOLF CREEK	615 - REPAIR/INSTALL GUARDRAIL	B	North approach	North approach has guardrail damage needs to be repaired.		0000
035-0026-0	Butts	WOLF CREEK ROAD	WOLF CREEK	800 - BRIDGE JOINT SEALING	C	Deck Joints	Deck joints need to be cleaned and sealed.		0000

035-0026-0	Butts	WOLF CREEK ROAD	WOLF CREEK	845 - OTHER BRIDGE MAINT	B	Bent #4	Bent 4; pile encasements need to be extended up to a point at least 2.0' above the water line.		0000
035-0026-0	Butts	WOLF CREEK ROAD	WOLF CREEK	845 - OTHER BRIDGE MAINT	B	Bent 3 column 1	Remove debris pile at bent 3 column 1.		0000
035-5004-0	Butts	RILEY ROAD	PLYMALE CREEK	415 - PIPE INSTALL/REPAIR	B	Both barrels	Repair Holes/Rust and corrosion		0000
035-5004-0	Butts	RILEY ROAD	PLYMALE CREEK	845 - OTHER BRIDGE MAINT	B	Debris at inlet	Large log inside barrel 1 inlet	8/10/2021	0000
035-5004-0	Butts	RILEY ROAD	PLYMALE CREEK	845 - OTHER BRIDGE MAINT	B	Inlet and Outlet ends	Inlet and outlet scour needs to be repaired.		0000
035-5005-0	Butts	WILDWOOD ROAD	CANEY FORK CREEK	520 - BRUSH AND TREE CUTTING	C	Both sides and in channel	Large amount of vegetation at the Inlet end and in the inlet channel needs to be cut and removed.	8/28/2019	0000
035-5005-0	Butts	WILDWOOD ROAD	CANEY FORK CREEK	550 - EROSION CONTROL	C	Behind both inlet wings	Repair erosion behind both inlet wings.		0000
035-5005-0	Butts	WILDWOOD ROAD	CANEY FORK CREEK	821 - CULVERT REPAIR	B	Throughout	1/8" to 1/4" vertical and horizontal cracking of the barrels, floors, ceilings, and walls; moderate spalls with exposed rebar. Wing walls have cracked and separated. Barrel #2 forward wall, fillet cracking going into culvert for 25' -- 1/4" wide down to hairline. Needs to be repaired.		0000
035-5005-0	Butts	WILDWOOD ROAD	CANEY FORK CREEK	845 - OTHER BRIDGE MAINT	B	Forward approach roadway.	Forward approach roadway has a dip at end of structure and needs to be leveled.		0000
035-5005-0	Butts	WILDWOOD ROAD	CANEY FORK CREEK	845 - OTHER BRIDGE MAINT	B	Underneath	Voids under culvert with water flowing underneath needs to be repaired. No water flowing in barrels.		0000
035-5014-0	Butts	ROCKY CREEK ROAD	ROCKY CREEK	821 - CULVERT REPAIR	B	All pipes	Repair holes in the bottom of pipes. Replace bituminous lining.		0000
035-5020-0	Butts	NATHAN THAXTON RD	BIG SANDY CREEK	520 - BRUSH AND TREE CUTTING	C	Inlet and outlet	Cut and remove vegetation		0000
035-5020-0	Butts	NATHAN THAXTON RD	BIG SANDY CREEK	821 - CULVERT REPAIR	B	Rear outlet wing	Repair moderate vertical cracking.		0000
035-5020-0	Butts	NATHAN THAXTON RD	BIG SANDY CREEK	845 - OTHER BRIDGE MAINT	B	all barrels	remove silt in barrels		0000
035-5025-0	Butts	JOE LANE ROAD	LEE CREEK	520 - BRUSH AND TREE CUTTING	C	Both sides	Large amount of vegetation on both ends needs to be cut and removed.		0000
035-5025-0	Butts	JOE LANE ROAD	LEE CREEK	821 - CULVERT REPAIR	B	Rear left wing	Rear left wing is cracked and separated 4-6' from barrel; Up to 5" wide at the top; Leaning 2" and needs to be repaired.		0000
035-5025-0	Butts	JOE LANE ROAD	LEE CREEK	845 - OTHER BRIDGE MAINT	B	Inlet	Repair Scour. Remove inlet drift and debris accumulation.		0000
035-5026-0	Butts	DEAN PATRICK ROAD	TOWALIGA RIVER TRIB	520 - BRUSH AND TREE CUTTING	C	Culvert	Brush needs to be cleared from culvert top		0000
035-5026-0	Butts	DEAN PATRICK ROAD	TOWALIGA RIVER TRIB	845 - OTHER BRIDGE MAINT	B	Inlet and Outlet	repair scour		0000
035-5026-0	Butts	DEAN PATRICK ROAD	TOWALIGA RIVER TRIB	845 - OTHER BRIDGE MAINT	B	Inlet wingwall	Repair erosion		0000

035-5027-0	Butts	KINARDS MILL ROAD	TOWALIGA RIVER	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Beams and bearings	Beams and bearings need to be cleaned and painted.		0000
035-5027-0	Butts	KINARDS MILL ROAD	TOWALIGA RIVER	800 - BRIDGE JOINT SEALING	C	Deck Joints	Deck joints need to be cleaned and sealed.		0000
035-5027-0	Butts	KINARDS MILL ROAD	TOWALIGA RIVER	810 - DECK REPAIR	B	Deck top	Repair minor spalls at the deck joints.		0000
035-5027-0	Butts	KINARDS MILL ROAD	TOWALIGA RIVER	845 - OTHER BRIDGE MAINT	B	Abutment 1	Abutment 1 has erosion underneath that needs to be repaired.		0000
035-5028-0	Butts	FILL BRIDGE ROAD	TOWALIGA RIVER TRIB	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	B	Beams	Beams need to be cleaned and painted.		0000
035-5028-0	Butts	FILL BRIDGE ROAD	TOWALIGA RIVER TRIB	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Beams	beams need to be cleaned and painted.		0000
035-5028-0	Butts	FILL BRIDGE ROAD	TOWALIGA RIVER TRIB	810 - DECK REPAIR	B	Deck Runners	Repair/replace deteriorated deck runners.	5/24/2016	0000
035-5028-0	Butts	FILL BRIDGE ROAD	TOWALIGA RIVER TRIB	845 - OTHER BRIDGE MAINT	B	Upstream	Beaver dam 2.5' high underneath structure		0000
035-5032-0	Butts	INDIAN CREEK ROAD	INDIAN CREEK	845 - OTHER BRIDGE MAINT	B	Abutment 3 and Jersey barriers	Repair erosion at Abutment 3. Remove graffiti from both concrete bridge rails.		0000
035-5034-0	Butts	COLWELL ROAD	CABIN CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	All Steel elements	All Steel elements need to be cleaned and painted.		0000
035-5034-0	Butts	COLWELL ROAD	CABIN CREEK	550 - EROSION CONTROL	B	Abutment 1	Abutment 1 has erosion 4" high x full width.		0000
035-5034-0	Butts	COLWELL ROAD	CABIN CREEK	800 - BRIDGE JOINT SEALING	C	All Joints	Clean and seal Joints		0000
035-5034-0	Butts	COLWELL ROAD	CABIN CREEK	845 - OTHER BRIDGE MAINT	B	Bearings	Several of the bearings have loose nuts that need to be tightened down.		0000
035-5037-0	Butts	BROWNLEE ROAD	BIG SANDY CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Bents 2, 3, and 4.	All steel piles need to be cleaned and painted		0000
035-5037-0	Butts	BROWNLEE ROAD	BIG SANDY CREEK	800 - BRIDGE JOINT SEALING	C	all joints	Deck joints need to be cleaned and sealed.		0000
035-5037-0	Butts	BROWNLEE ROAD	BIG SANDY CREEK	800 - BRIDGE JOINT SEALING	C	deck joints	deck joints need cleaning and sealing.		0000

035-5037-0	Butts	BROWNLEE ROAD	BIG SANDY CREEK	830 - REP MAIN STRUCT MEMBERS	B	Bent 3	Piles 1 and 2 encasements are undermined and need to be extended to a point 2.0' below the mudline.		0000
035-5037-0	Butts	BROWNLEE ROAD	BIG SANDY CREEK	845 - OTHER BRIDGE MAINT	B	Bent 4	Repair moderate to severe scour at piles 1 and 2.		0000
035-5039-0	Butts	FINCHERVILLE ROAD	TUSSAHAW CREEK TRIB	845 - OTHER BRIDGE MAINT	B	North end, downstream	Fill void under Northern wall down stream.		0000
035-5041-0	Butts	GILES FERRY ROAD	DOUGLAS CREEK	821 - CULVERT REPAIR	B	All barrel	All barrels have rust and corrosion and barrel 2 has a 40' section of pipe with holes in pipe and 100 section loss.	LMIG	0000
035-5041-0	Butts	GILES FERRY ROAD	DOUGLAS CREEK	821 - CULVERT REPAIR	B	Pipes 1 and 2	Pipe 1 inlet, a 3.0' section is turned up restricting flow and needs to be repaired. Pipe 2, downward distortion needs to be repaired/stabilized.	LMIG	0000
035-5041-0	Butts	GILES FERRY ROAD	DOUGLAS CREEK	845 - OTHER BRIDGE MAINT	B	All pipes	After pipe corrosion has been repaired; lining in the bottom 1/3 of pipes needs to be replaced/added.	LMIG	0000
035-5041-0	Butts	GILES FERRY ROAD	DOUGLAS CREEK	845 - OTHER BRIDGE MAINT	B	Inlet	Large amount of drift and debris accumulation at inlet needs to be removed.	LMIG	0000
035-5041-0	Butts	GILES FERRY ROAD	DOUGLAS CREEK	845 - OTHER BRIDGE MAINT	B	Outlet	Repair outlet scour	LMIG	0000
035-5042-0	Butts	LOCUST ROAD	INDIAN CREEK TRIB	415 - PIPE INSTALL/REPAIR	B	All pipes	Repair corrosion/holes and replace lining.		0000
035-5042-0	Butts	LOCUST ROAD	INDIAN CREEK TRIB	520 - BRUSH AND TREE CUTTING	C	Both ends	Large amount of vegetation needs to be cut and removed.		0000
035-5042-0	Butts	LOCUST ROAD	INDIAN CREEK TRIB	845 - OTHER BRIDGE MAINT	B	inlet and outlet	Repair scour inlet and outlet. 2021; Scour has silted in.	8/16/2021	0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	All steel piles	All steel piles need to be cleaned and painted.		0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	150 - MAINTENANCE RESURFACING	B	Both approach roadways	Both approach roadways have minor settlement and need to be leveled.	LMIG	0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	550 - EROSION CONTROL	B	Abutment 5	Abutment 5 left has erosion 8.0' long x 2.0' wide x 2.0' deep and needs to be repaired.		0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	800 - BRIDGE JOINT SEALING	C	Deck joints	Deck joints need to be cleaned and sealed.		0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	845 - OTHER BRIDGE MAINT	B	Bent 3	Remove drift and debris accumulation from bent 3. Completed 8-23-2021	8/23/2021	0000
035-5043-0	Butts	CENIE ROAD	BIG SANDY CREEK	845 - OTHER BRIDGE MAINT	B	Bents 2 and 3	Encasements at bent 2, piles 1 and 2 are at the ground line Bent 3 piles 1, 3, and 5 are undermined and need to be extended to a point 2.0' below the mud line.		0000
035-5045-0	Butts	MAYFIELD ROAD	LITTLE SANDY CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Bent 2	Piles at bent 2 and beams need to be cleaned and painted.		0000

035-5045-0	Butts	MAYFIELD ROAD	LITTLE SANDY CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Steel piles and beams need to be cleaned and painted	Steel piles and beams need to be cleaned and painted		0000
035-5045-0	Butts	MAYFIELD ROAD	LITTLE SANDY CREEK	830 - REP MAIN STRUCT MEMBERS	B	Bent 2 cap	Repair spalls in bent 2 cap.		0000
035-5046-0	Butts	VICKER ROAD	LITTLE SANDY CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Various beams	Various beams have paint beginning to peel and flake. Needs to be cleaned and painted.		0000
035-5047-0	Butts	FINCHERVILLE ROAD	TUSSAHAW CREEK	800 - BRIDGE JOINT SEALING	C	Deck joint 1	Abutment 1 deck joint has moderate adhesion loss and needs to be cleaned and sealed.		0000
035-5047-0	Butts	FINCHERVILLE ROAD	TUSSAHAW CREEK	810 - DECK REPAIR	B	Abutment 8	Deck spall at abutment 8 joint		0000
035-5049-0	Butts	ROY BELL ROAD	BRUSHY CREEK	845 - OTHER BRIDGE MAINT	B	Inlet and Outlet	Repair scour inlet and outlet		0000
035-5051-0	Butts	PRATT SMITH RD	PANTHER CREEK	000 - BRIDGE PAINTING (Not performed by Highway Maintenance, used by Bridge Mntce)	C	Piles	Piles need to be cleaned and painted		0000
035-5051-0	Butts	PRATT SMITH RD	PANTHER CREEK	845 - OTHER BRIDGE MAINT	B	Rear approach	Level Rear approach pavement		0000
035-5054-0	Butts	DOUGLAS CREEK ROAD	PLYMALE CREEK	845 - OTHER BRIDGE MAINT	B	Inlet	Beaver dam across all inlet barrels.		0000
035-5054-0	Butts	DOUGLAS CREEK ROAD	PLYMALE CREEK	845 - OTHER BRIDGE MAINT	B	Outlet	Repair scour at outlet end.		0000